

8/31/2016, Rachel Savich Oser, Fbk. 48, pg. 7

8/23/2018, Cassidy Raley, Fbk. 52, pg. 22

Monument recovered in good condition, 0.4' below grade

Added t-post and MCSO Sign


Corner I.D. # 109T

MONUMENT RECORD

STATE OF INDIANA ~ COUNTY OF MONROE

Section 28, Township 7N, Range 1W,


Monument Description & Remarks: 2-1/2" Aluminum Monument, 30" long, set 0.1' below grade.
(This monument is not a PLSS corner. It was set as part of a Geodetic Control Survey.)



I, Matthew L. Cooper, here by certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; this 9th day of June, 2004 A.D.

Indiana Registered Land Surveyor No. LS20200079

COMPLETED By *St. V. Tanks*



0 50 100 200 Feet

ImageSource: 2014 Monroe County Pictometry



**Office of the Monroe County Surveyor
2004 Geodetic Control Project**

119 West 7th Street
Bloomington, Indiana 47404
(812) 349-2570

